

## Rumrill, Nancy

---

**From:** Jennifer Saran <JenniferSaran@florencecopper.com>  
**Sent:** Friday, November 12, 2021 12:16 PM  
**To:** Rumrill, Nancy  
**Cc:** Brent Berg  
**Subject:** follow up items  
**Attachments:** ATT00001.txt

Good afternoon,

In response to our phone conversations on November 10 and 12, 2021, please see the two follow up items detailed below:

### Verification rinse well

The verification rinse wells will be located within the wellfield, will be used as early warning monitoring, and will be sampled for Level I parameters. Sulfate will be used as the indicator parameter: If sulfate concentrations in the verification rinse well exceed 750 ppm, the monitoring frequency of the POCs wells will be increased.

### Attachment E

The PTF wells were included in the original version of Attachment E, on Table E17 and E23.

Florence Copper has annotated Tables E17 and E23 (PDF Pages 92-93 and 121 – 122) to indicate which wells are existing PTF wells.

No other changes were made to the Attachment.

Please follow the link below to download the updated version of UIC Application Attachment E.

<https://haleyaldrich.sharefile.com/d-s5d96e5a5fd0e4f27a075d31c98a2f1d2>

If you have any questions on this information, or need anything else, please let me know.

Thanks,  
Jennifer

**Jennifer Saran** Environmental, Health and Safety Manager



Florence Copper Inc.  
1575 W. Hunt Highway Florence AZ USA 85132  
C 480-532-0108 T 520-316-3707 F 520-374-3999  
E [jennifersaran@florencecopper.com](mailto:jennifersaran@florencecopper.com) Web [florencecopper.com](http://florencecopper.com)

**SAFETY – Own it. Practice it. Share it.**  
**#FLORENCECOPPERSTRONG**

---

"Notice Regarding Transmission

This message is intended only for the person(s) to whom it is addressed and may contain information that is privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination or copying of this communication is prohibited. Please notify us of the error in communication by telephone (778-373-4533) or by return e-mail and destroy all copies of this communication. Please note that any views or opinions presented in this email are solely those of the author and do not necessarily represent those of Taseko Mines Limited or any affiliated or associated company. The recipient should check this email and any attachments for the presence of viruses. Neither Taseko Mines Limited nor any affiliated or associated company accepts any liability for any damage caused by any virus transmitted by this email. Thank you."